

Biennial Bridge Inspection Report

Niska Road Over Speed River Bridge

No. 00001

April 14, 2014



Prepared By: Engineered Management Systems Inc.

42 Lakeshore Road East, Suite B
Mississauga, Ontario
L5G 1C8

T.905.891.9524
F.866.839.8471

405 Riverview Drive, Suite 302
Chatham, Ontario
N7M 5J5



engineered management systems inc.

IMPORTANT

Limitations

Data presented in this report is essentially a snapshot of value, condition, needs and their associated cost as per the date of inspection. Replacement costs, remaining service life assessments, condition Indices and AADT projections continually change over time. Continued deterioration, inflation and, to a lesser extent, increasing traffic volumes, create a dynamic environment that must be effectively modeled before any long range planning is possible.

Recommendations and cost estimates (when provided) put forward are strictly preliminary. They are based on a visual "from the ground" assessment and are intended for budgetary and planning purposes only. A far more detailed and exhaustive analysis should be provided during detailed design that addresses all deficiencies AND full compliance with the CHBDC.

Urgencies


Throughout this report the reader will see reference to the term "Urgencies". These are essentially time frames that the inspector must attempt to predict, on-site, on an element-by-element basis, as to how long the recommended work can wait to be addressed before it becomes critical.

Urgencies are essentially included as a requirement of the OSIM guidelines. We apply a similar evaluation called Remaining Service Life. It is a more flexible system as it provides, in many cases, more than one time frame depending on the agency's in-house capabilities to carry out basic maintenance of their inventory. RSL's do NOT drive the management process nor do they participate in optimization except as fail safe points beyond which certain issues must be addressed during scheduling.

Respectfully Submitted:



engineered management systems inc.



Structure Summary


00001 - Niska Road Over Speed River




Type	Truss	Replacement Cost	\$1,168,950
Year Built	1974	Rehabilitative Needs	\$1,020,000
Last Rehabilitated	N/A	Condition Index	12.7
		Est. 10 Yr. Deferral Cost	\$229,694
GPS East	17560310	AADT	3700
GPS North	4816872		
Location :			
Niska Road			
0.64km West of Pioneer Trail			

General Comments :
The major concerns at this site are structural inadequacy of structure, water encroaching against abutments, road constriction, structural inadequacy of barriers, absence of a pedestrian access, absence of a traffic barrier, progressive undermining of the northwest retaining wall, severe failure of the northwest embankment, partial failure of northeast embankment, structural inadequacy of signage, severe corrosion of the bearing plates, isolated severe corrosion of the bottom chords at the ends and west end verticals, partial poor condition and progressive deterioration of the bearing seats and progressive deterioration of the masonry retaining walls.


Distribution of \$1,168,950 Replacement Value



Distribution of \$1,020,000 Rehabilitation Cost



Safety Risk



Risk assessed on a scale of 0 to 100 based on estimated RSL and the safety critical nature of the component and its observed defects. Intended as a guide only and not to be taken out of context with the detailed findings of this report.

Network Comparison

Replacement Value	21 / 69
Rehabilitative Needs	6 / 69
Condition Index	62 / 69
Est. 10 Year Deferral Cost	10 / 69
AADT	20 / 69




Table Of Contents

1. Narrative	1
1.1 Introduction	1
1.2 General Information	1
1.3 Observations	1
1.3.1 East Approach	1
1.3.2 West Approach	1
1.3.3 Deck	1
1.3.4 East Transverse Joint	1
1.3.5 West Transverse Joint	2
1.3.6 Sidewalk/Curb/Median	2
1.3.7 Barrier	2
1.3.8 Signage	2
1.3.9 Truss	2
1.3.10 Floor Beams	2
1.3.11 Stringers	3
1.3.12 Bracing	3
1.3.13 East Abutment	3
1.3.14 West Abutment	3
1.3.15 East Retaining Wall	4
1.3.16 West Retaining Wall	4
1.3.17 East Embankment	4
1.3.18 West Embankment	4
1.3.19 Foundation	5
1.3.20 Watercourse	5
1.4 Conclusions and Further Investigation	5
1.4.1 Rehabilitative	5
1.4.2 Pre-Emptive	7
1.4.3 Maintenance	7
1.4.4 Further Investigation	8
1.5 Statistical Summary	9
2. Component Summary	10
3. Element Summary	11
4. Maintenance Summary	14
5. Ranking Summary	16
6. OSIM Reporting	17
6.1 Inventory Data	17
6.2 Historical Data	17

Table of Contents (cont.)

6.3 Scheduled Improvements	18
6.4 Appraisal Indices	18
6.5 Field Inspection Information	19
6.6 Additional Investigations Required	19
6.7 Element Data	20
6.7.1 West Approach - Approach	20
6.7.2 East Approach - Approach	21
6.7.3 West Approach - Slab	22
6.7.4 East Approach - Slab	23
6.7.5 West Approach - Wearing Surface	24
6.7.6 East Approach - Wearing Surface	25
6.7.7 Deck - Deck	26
6.7.8 Deck - Soffit Ends	27
6.7.9 Deck - Interior Soffit	28
6.7.10 Deck - Top Surface	29
6.7.11 West Transverse Joint - Transverse Joint	30
6.7.12 East Transverse Joint - Transverse Joint	31
6.7.13 Sidewalk/Curb/Median - SouthSidewalk/Curb/Median	32
6.7.14 Sidewalk/Curb/Median - North Curb	33
6.7.15 Barrier - Barrier	34
6.7.16 Signage - Signage	35
6.7.17 Truss - Truss	36
6.7.18 Truss - Bottom Chords	37
6.7.19 Truss - Diagonals	38
6.7.20 Truss - Top Chords	39
6.7.21 Truss - Connections	40
6.7.22 Truss - Verticals	41
6.7.23 Floor Beams - Floor Beams	42
6.7.24 Floor Beams - Floor Beam Ends	43
6.7.25 Floor Beams - Intermediate Floor Beams	44
6.7.26 Stringers - Stringers	45
6.7.27 Stringers - Middle Stringers	46
6.7.28 Bracing - Bracing	47
6.7.29 Bracing - East End Bracing	48
6.7.30 Bracing - Intermediate Bracing	49
6.7.31 Bracing - West End Bracing	50
6.7.32 West Abutment - Abutment	51

Table of Contents (cont.)

6.7.33 East Abutment - Abutment	52
6.7.34 West Abutment - Bottom Abutment Wall	53
6.7.35 East Abutment - Bottom Abutment Wall	54
6.7.36 West Abutment - Bearings	55
6.7.37 East Abutment - Bearings	56
6.7.38 West Abutment - Bearing Seats	57
6.7.39 East Abutment - Bearing Seats	58
6.7.40 West Abutment - Abutment Wall	59
6.7.41 East Abutment - Abutment Wall	60
6.7.42 West Abutment - Ballast Wall	61
6.7.43 East Abutment - Ballast Wall	62
6.7.44 West Retaining Wall - NorthRetaining Wall	63
6.7.45 West Retaining Wall - Vertical Surface	64
6.7.46 East Retaining Wall - SouthRetaining Wall	65
6.7.47 West Retaining Wall - SouthRetaining Wall	66
6.7.48 East Retaining Wall - South Vertical Surface	67
6.7.49 West Retaining Wall - South Vertical Surface	68
6.7.50 East Retaining Wall - NorthRetaining Wall	69
6.7.51 West Retaining Wall - NorthRetaining Wall	70
6.7.52 East Retaining Wall - North Vertical Surface	71
6.7.53 West Retaining Wall - North Vertical Surface	72
6.7.54 West Embankment - Embankment	73
6.7.55 East Embankment - Embankment	74
6.7.56 West Embankment - Slope Protection	75
6.7.57 East Embankment - Slope Protection	76
6.7.58 Foundation - Foundation	77
6.7.59 Foundation - NorthFoundation	78
6.7.60 Watercourse - Watercourse	79
6.7.61 Watercourse - Bottom	80
6.7.62 Watercourse - Downstream Section	81
6.7.63 Watercourse - Upstream Section	82
7. Glossary	83

1. Narrative

1.1 Introduction

The inspection summarized in this report was undertaken in compliance with the requirements of the Public Transportation and Highway Improvement Act, Ontario Regulation 104/97. The last known detailed visual inspection of this structure took place in 2012. The inspection was carried out on Monday, April 14, 2014 by Lin Yu under the direction of M. Wallrap P. Eng. At the time of inspection it was sunny with temperatures between 5 and 10 degrees celsius. This report meets or exceeds all requirements for detailed visual surveys as set out in the Ontario Structure Inspection Manual 2000, rev. 2003, 2008.

1.2 General Information

The Niska Road Over Speed River bridge was built in 1974. The structure has a West-East orientation and is located on Niska Road 0.64 km West of Pioneer Trail in the City of Guelph. This Truss bridge carries 1 lane of vehicular traffic across the Speed River in 1 continuous span with a crossing length of 24.6m and a maximum clearance of 2.7m. The deck has a travel width of 3.44m and an overall width of 5.5m.

With an AADT of 3,700 the crossing is lightly used with truck volumes accounting for less than 10% of the total traffic. The speed limit at this location is 50 km/hr. There is a posted load limit of 5tonnes There is no record of rehabilitation for this structure. This is not considered a heritage structure. The total estimated replacement value is \$1,168,950.

1.3 Observations

Each component is presented along with a discussion of any elements within that component that exhibit notable deterioration and/or a low estimated remaining service life. Thorough documentation of every element in the structure can be found in the detailed forms in Section 6.7 - Element Data.

The Niska Road Over Speed River bridge is comprised of the following components:

1.3.1 East Approach

The asphalt approach has an estimated mass of 5.81 tonnes. . The estimated remaining service life in its current condition is 10 years. No significant defects were noted, however, the entire component will undergo ancillary replacement.

1.3.2 West Approach

The asphalt approach has an estimated mass of 5.81 tonnes. . The estimated remaining service life in its current condition is 10 years. No significant defects were noted, however, the entire component will undergo ancillary replacement.

1.3.3 Deck

The timber deck has an estimated mass of 8 tonnes. An estimated 5% of the element exhibits severe general deterioration. The estimated remaining service life in its current condition is 10 years. The entire component will undergo ancillary replacement.

The top surface has a surface area of 84.6 square metres. Approximately 10% of the element exhibits severe checking.

1.3.4 East Transverse Joint

No significant defects were noted.

1. Narrative (cont.)

1.3.5 West Transverse Joint

No significant defects were noted.

1.3.6 Sidewalk/Curb/Median

The timber south sidewalk/curb/median has an estimated mass of 0.5 tonnes. An estimated 15% of the element exhibits medium general deterioration. The estimated remaining service life in its current condition is 10 years. The entire component will undergo ancillary replacement.

The north curb has a surface area of 18.6 square metres. A significant portion of the element exhibits medium checking.

1.3.7 Barrier

The timber barrier has an estimated mass of 0.2 tonnes. The element is structurally inadequate. Maintenance work is required immediately to extend the service life of the element. There is no estimated service life remaining in its current condition. The entire component will undergo ancillary replacement.

1.3.8 Signage

There are 6 aluminum signage. The element is structurally inadequate. Maintenance work is required to extend the service life of the element. The estimated remaining service life in its current condition is 1 year. The entire component will undergo ancillary replacement.

1.3.9 Truss

The steel truss have an estimated mass of 25 tonnes. An estimated 2% of the element exhibits severe general deterioration. Maintenance work is required to extend the service life of the element. The estimated remaining service life in its current condition is 5 years. The entire component will undergo ancillary replacement.

The bottom chords have a surface area of 78.1 square metres. Less than 5% of the element exhibits severe corrosion.

The top chords have a surface area of 80.5 square metres. Approximately 10% of the element exhibits light corrosion.

The verticals have a surface area of 38.4 square metres. Less than 5% of the element exhibits severe corrosion.

1.3.10 Floor Beams

The timber floor beams have an estimated mass of 4.4 tonnes. An estimated 5% of the element exhibits light general deterioration. The estimated remaining service life in its current condition is 20 years. The entire component will undergo ancillary replacement.

The floor beam ends have a surface area of 11.25 square metres. Approximately 10% of the element exhibits light corrosion.

The intermediate floor beams have a surface area of 62 square metres. Approximately 10% of the element exhibits light corrosion.

1. Narrative (cont.)

1.3.11 Stringers

The steel stringers have an estimated mass of 4.5 tonnes. An estimated 8% of the element exhibits medium general deterioration. The estimated remaining service life in its current condition is 10 years. The entire component will undergo ancillary replacement.

The middle stringers have a surface area of 146.4 square metres. Approximately 10% of the element exhibits medium corrosion.

1.3.12 Bracing

The steel bracing has an estimated mass of 1 tonne. . The estimated remaining service life in its current condition is 15 years. No significant defects were noted, however, the entire component will undergo ancillary replacement.

1.3.13 East Abutment

The masonry abutment has an estimated mass of 46 tonnes. An estimated 20% of the element exhibits severe general deterioration. The estimated remaining service life in its current condition is 2 years.

The lower abutment wall has a surface area of 1.5 square metres. The entire element exhibits severe splitting and replacement is warranted.

There are 2 plate bearings. Most of the elements exhibit severe corrosion and replacement is warranted.

There are 2 ledge type bearing seats. A significant portion of the elements exhibit severe disintegration requiring loaded deep repair.

The abutment wall has a surface area of 11.5 square metres. Approximately 10% of the element exhibits severe loss of mortar and replacement is warranted.

1.3.14 West Abutment

The masonry abutment has an estimated mass of 46 tonnes. An estimated 20% of the element exhibits severe general deterioration. The estimated remaining service life in its current condition is 2 years.

The lower abutment wall has a surface area of 0.5 square metres. The entire element exhibits severe splitting and replacement is warranted.

There are 2 plate bearings. Most of the elements exhibit severe corrosion and replacement is warranted.

There are 2 ledge type bearing seats. A significant portion of the elements exhibit severe disintegration requiring loaded deep repair.

The abutment wall has a surface area of 12.5 square metres. Approximately 10% of the element exhibits severe loss of mortar and replacement is warranted.

The ballast wall has a surface area of 3 square metres. A significant portion of the element exhibits very severe splitting requiring timber replacement.

1. Narrative (cont.)

1.3.15 East Retaining Wall

The masonry south gravity retaining wall has an estimated mass of 33.41 tonnes. An estimated 40% of the element exhibits severe general deterioration. The estimated remaining service life in its current condition is 5 years. The entire component will undergo ancillary replacement.

The south vertical surface has a surface area of 17.4 square metres. Much of the element exhibits severe loss of mortar.

The masonry north gravity retaining wall has an estimated mass of 36.72 tonnes. An estimated 5% of the element exhibits severe general deterioration. The estimated remaining service life in its current condition is 10 years. The entire component will undergo ancillary replacement.

The north vertical surface has a surface area of 25.5 square metres. Approximately 10% of the element exhibits severe loss of mortar.

1.3.16 West Retaining Wall

The mass concrete north gravity retaining wall has an estimated mass of 18.29 tonnes. An estimated 20% of the element exhibits medium general deterioration. The estimated remaining service life in its current condition is 10 years. The entire component will undergo ancillary replacement.

The vertical surface has a surface area of 14 square metres. The entire element exhibits medium loss of mortar.

The masonry south gravity retaining wall has an estimated mass of 26.88 tonnes. An estimated 5% of the element exhibits medium general deterioration. The estimated remaining service life in its current condition is 5 years. The entire component will undergo ancillary replacement.

The south vertical surface has a surface area of 14 square metres. Approximately 10% of the element exhibits severe loss of stone.

The masonry north gravity retaining wall has an estimated mass of 26.88 tonnes. The entire element exhibits medium general deterioration. The estimated remaining service life in its current condition is 5 years. The entire component will undergo ancillary replacement.

The north vertical surface has a surface area of 12.7 square metres. A significant portion of the element exhibits light settlement.

1.3.17 East Embankment

The soil embankment has a surface area of 45 square metres. An estimated 20% of the element exhibits severe general deterioration. The estimated remaining service life in its current condition is 5 years.

The slope protection has a surface area of 45 square metres. A significant portion of the element exhibits partial failure requiring restoration.

1.3.18 West Embankment

The soil embankment has a surface area of 45 square metres. An estimated 40% of the element exhibits severe general deterioration and replacement is warranted. The estimated remaining service life in its current condition is 1 year.

The slope protection has a surface area of 45 square metres. Much of the element exhibits partial failure.

1. Narrative (cont.)

1.3.19 Foundation

The steel piles foundation has an effective surface area of 65 square metres. An estimated 20% of the element exhibits severe erosion requiring reinstallation. The estimated remaining service life in its current condition is 1 year.

The steel piles north foundation has an effective surface area of 11.5 square metres. An estimated 20% of the element exhibits very severe erosion requiring reinstallation. The estimated remaining service life in its current condition is 1 year.

1.3.20 Watercourse

The natural bottom has a surface area of 120.54 square metres. A significant portion of the element exhibits medium degradation although no immediate rehabilitative action is required.

The uncontrolled upstream section has a surface area of 60.27 square metres. A significant portion of the element exhibits severe misalignment requiring redirection.

1.4 Conclusions and Further Investigation

Overall the structure is in poor condition with an aggregate condition index of 12.7. The major concerns at this site are structural inadequacy of structure, water encroaching against abutments, road constriction, structural inadequacy of barriers, absence of a pedestrian access, absence of a traffic barrier, progressive undermining of the northwest retaining wall, severe failure of the northwest embankment, partial failure of northeast embankment, structural inadequacy of signage, severe corrosion of the bearing plates, isolated severe corrosion of the bottom chords at the ends and west end verticals, partial poor condition and progressive deterioration of the bearing seats and progressive deterioration of the masonry retaining walls.

1.4.1 Rehabilitative

The following summarizes the rehabilitative needs of the structure:

West Approach

Ancillary Replacement

East Approach

Ancillary Replacement

Deck

Ancillary Replacement

Sidewalk/Curb/Median - South

Ancillary Replacement

Barrier

Ancillary Replacement

Signage

Ancillary Replacement

Truss

Ancillary Replacement

1. Narrative (cont.)

Floor Beams

Ancillary Replacement

Stringers

Ancillary Replacement

Bracing

Ancillary Replacement

West Abutment - Bottom Abutment Wall

Replacement

East Abutment - Bottom Abutment Wall

Replacement

West Abutment - Bearings

Replacement

East Abutment - Bearings

Replacement

West Abutment - Bearing Seats

Loaded Deep Repair

East Abutment - Bearing Seats

Loaded Deep Repair

West Abutment - Abutment Wall

Replacement

East Abutment - Abutment Wall

Replacement

West Abutment - Ballast Wall

Timber Replacement

West Retaining Wall - North

Ancillary Replacement

East Retaining Wall - South

Ancillary Replacement

West Retaining Wall - South

Ancillary Replacement

East Retaining Wall - North

Ancillary Replacement

West Retaining Wall - North

Ancillary Replacement

1. Narrative (cont.)

West Embankment

Replacement

East Embankment - Slope Protection

Restoration

Foundation

Reinstallation

Foundation - North

Reinstallation

Watercourse - Upstream Section

Redirection

1.4.2 Pre-Emptive

No pre-emptive measures are currently recommended or required.

1.4.3 Maintenance

On-going maintenance procedures should be part of an annual regimen. Often these operations can be carried out by municipal staff however cost estimates have been provided in cases where it may be contracted out.

West Transverse Joint

Power Washing

East Transverse Joint

Power Washing

Barrier

Minor Repair, Removal or Installation

Signage

Minor Repair, Removal or Installation

Truss - Bottom Chords

Minor Repair, Removal or Installation

Truss - Verticals

Minor Repair, Removal or Installation

West Abutment - Ballast Wall

Minor Repair, Removal or Installation

Foundation

Scour Protection

Foundation - North

Scour Protection

1. Narrative (cont.)


1.4.4 Further Investigation

The next biennial inspection should be scheduled no later than April, 2016. In addition, a monitoring program for deformations, settlements & movements should be carried out immediately.


1. Narrative (cont.)

1.5 Statistical Summary


Distribution of \$1,168,950 Replacement Value



Distribution of \$1,020,000 Rehabilitation Cost



Safety Risk



Risk assessed on a scale of 0 to 100 based on estimated RSL and the safety critical nature of the component and its observed defects. Intended as a guide only and not to be taken out of context with the detailed findings of this report.

2. Component Summary

	Replacement	RSL		Maint.	Pre-Emp	Urgent	Urgency of Rehabilitative Needs			
		1	2				< 1 year	1 - 5 years	6 - 10 years	None>10 yrs
East Approach	\$950	10	10						\$1,500	
West Approach	\$950	10	10						\$1,500	
Deck	\$15,000	10	10						\$15,000	
East Transverse Joint	\$15,000	15	15	\$300						
West Transverse Joint	\$15,000	15	15	\$300						
Sidewalk/Curb/Median	\$300	10	10						\$1,500	
Barrier	\$250	0	10	\$300		\$1,500				
Signage	\$2,000	1	10	\$300			\$2,000			
Truss	\$450,000	5	10	\$910				\$500,000		
Floor Beams	\$5,500	20	20							\$6,000
Stringers	\$40,000	10	10						\$40,000	
Bracing	\$15,000	15	15							\$15,000
East Abutment	\$100,000	2	2					\$9,500		
West Abutment	\$100,000	2	2	\$300				\$9,500		
East Retaining Wall	\$100,000	5	5					\$115,000		
West Retaining Wall	\$95,000	5	5					\$99,000		
East Embankment	\$2,000	5	5					\$1,000		
West Embankment	\$2,000	1	1				\$2,000			
Foundation	\$200,000	1	1	\$666			\$175,000			
Watercourse	\$10,000	1	1				\$25,000			
Totals and Minimums	\$1,168,950	0	1	\$3,076	\$0	\$1,500	\$204,000	\$734,000	\$59,500	\$21,000
Total Estimated Rehabilitative Cost:										\$1,020,000
Contingency:										\$0
Provisional Allowance:										\$0
Total Potential Project Cost:										\$1,020,000

3. Element Summary

	Focus	RSL		Maint.	Pre-Emp.	Urgent	Urgency of Rehabilitative Needs			
		1	2				< 1 year	1 - 5 years	6 - 10 years	None>10 yrs
West Approach	All	10	10						\$1,500	
East Approach	All	10	10						\$1,500	
Slab	All	15	15							
Slab	All	15	15							
Wearing Surface	All	10	10							
Wearing Surface	All	10	10							
Deck	All	10	10						\$15,000	
Soffit Ends	Both	10	10							
Interior Soffit	Interior	10	10							
Top Surface	All	10	10							
West Transverse Joint	All	15	15	\$300						
East Transverse Joint	All	15	15	\$300						
Sidewalk/Curb/Median - South	All	10	10						\$1,500	
North Curb	All	10	10							
Barrier	All	0	10	\$300		\$1,500				
Signage	All	1	10	\$300			\$2,000			
Truss	All	5	10					\$500,000		
Bottom Chords	Bottom	5	10	\$610						
Diagonals	All	20	20							
Top Chords	Top	15	15							
Connections	All	15	15							
Verticals	All	5	10	\$300						
Floor Beams	All	20	20							\$6,000
Floor Beam Ends	End	20	20							
Intermediate Floor Beams	Interior	20	20							
Stringers	All	10	10						\$40,000	
Middle Stringers	Interior	10	10							
Bracing	All	15	15							\$15,000
East End Bracing	End	15	15							
Intermediate Bracing	All	15	15							

3. Element Summary (cont.)

	Focus	RSL		Maint.	Pre-Emp.	Urgent	Urgency of Rehabilitative Needs			
		1	2				< 1 year	1 - 5 years	6 - 10 years	None\>10 yrs
West End Bracing	End	15	15							
West Abutment	All	2	2							
East Abutment	All	2	2							
Bottom Abutment Wall	All	5	5					\$1,000		
Bottom Abutment Wall	All	5	5					\$3,500		
Bearings	All	2	2					\$2,500		
Bearings	All	2	2					\$2,500		
Bearing Seats	All	5	5					\$2,500		
Bearing Seats	All	5	5					\$2,500		
Abutment Wall	All	5	5					\$2,000		
Abutment Wall	All	5	5					\$1,000		
Ballast Wall	All	5	5	\$300				\$1,500		
Ballast Wall	All	10	10							
West Retaining Wall - North	Exterior	10	10						\$9,000	
Vertical Surface	All	10	10							
East Retaining Wall - South	All	5	5					\$55,000		
West Retaining Wall - South	All	5	5					\$45,000		
South Vertical Surface	All	5	5							
South Vertical Surface	All	5	5							
East Retaining Wall - North	All	10	10						\$60,000	
West Retaining Wall - North	All	5	5					\$45,000		
North Vertical Surface	All	10	10							
North Vertical Surface	All	5	5							
West Embankment	All	1	1				\$2,000			
East Embankment	All	5	5							
Slope Protection	All	1	1							
Slope Protection	All	5	5					\$1,000		
Foundation	All	1	1	\$366			\$150,000			
Foundation - North	West	1	1	\$300			\$25,000			
Watercourse	All	1	1							

3. Element Summary (cont.)

	Focus	RSL		Maint.	Pre-Emp.	Urgent	Urgency of Rehabilitative Needs			
		1	2				< 1 year	1 - 5 years	6 - 10 years	None\>10 yrs
Bottom	All	5	5							
Downstream Section	All	20	20							
Upstream Section	All	1	1				\$25,000			
Totals and Minimums		0	1	\$3,076	\$0	\$1,500	\$204,000	\$665,000	\$128,500	\$21,000
Total Estimated Rehabilitative Cost:										\$1,020,000
Contingency:										\$0
Provisional Allowance:										\$0
Total Potential Project Cost:										\$1,020,000

4. Maintenance Summary

Barrier

Observed Defect: [Structural Inadequacy](#)

Suggested Maintenance: [Minor Repair, Removal or Installation](#)



Signage

Observed Defect: [Structural Inadequacy](#)

Suggested Maintenance: [Minor Repair, Removal or Installation](#)



Truss - Bottom Chords - Bottom

Observed Defect: [Severe Corrosion](#)

Suggested Maintenance: [Minor Repair, Removal or Installation](#)



Truss - Verticals

Observed Defect: [Severe Corrosion](#)

Suggested Maintenance: [Minor Repair, Removal or Installation](#)



4. Maintenance Summary (cont.)

West Abutment - Ballast Wall

Observed Defect: [Very Severe Splitting](#)

Suggested Maintenance: [Minor Repair, Removal or Installation](#)



Foundation

Observed Defect: [Severe Erosion](#)

Suggested Maintenance: [Scour Protection](#)



Foundation - North - West

Observed Defect: [Very Severe Erosion](#)


Suggested Maintenance: [Scour Protection](#)



5. Ranking Summary


Replacement Value (millions)

This Structure: **\$1,168,950** Rank: **21 / 69**




AADT

This Structure: **3700** Rank: **20 / 69**




Rehabilitative Needs (millions)

This Structure: **\$1,020,000** Rank: **6 / 69**




Condition Index

This Structure: **12.7** Rank: **62 / 69**



Est. 10 Year Deferral Cost (millions)

This Structure: **\$229,694** Rank: **10 / 69**



Notes:

Data calculated at time of inspection.

Rankings are highest in category.

Histograms illustrate distribution of all structures in inventory from the low to high ranges indicated.

Vertical axis = number of structures.

Red columns represent category in which this structure resides.

6. OSIM Reporting

6.1 Inventory Data

Structure Name	Niska Road Over Speed River		Site Number	00001	
Main Hw y/Road #	N/A	On <input checked="" type="checkbox"/> Under <input type="checkbox"/>	Crossing Type:	Navigable Water <input checked="" type="checkbox"/> Non-Navig. Water <input type="checkbox"/>	
Hw y/Road Name	Niska Road		Rail	<input type="checkbox"/>	Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other <input type="checkbox"/>
Structure Location	NA Park - NA				
Latitude	4816872		Longitude	17560310	
Owner(s)	City of Guelph		Heritage Designation:	Not Cons. <input checked="" type="checkbox"/> Cons./Not App. <input type="checkbox"/> List/Not Desig. <input type="checkbox"/>	
				Desig./Not List <input type="checkbox"/> Desig. & List <input type="checkbox"/>	
MTO Region	SouthWestern		Road Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input checked="" type="checkbox"/>	
MTO District	London/Stratford		Posted Speed	50	No. of Lanes 1
Old County	Wellington		AADT	3700	No. of Trucks 7
Geographic Tw p.	City of Guelph		Inspection Route Sequence	Unknown	
Structure Type	Truss		Interchange Number	Unknown	
Total Deck Length	24.6	(m)	Interchange Structure Number	Unknown	
Overall Str. Width	5.5	(m)	Minimum Vertical Clearance	0	(m)
Total Deck Area	135.3	(sq.m)	Special Routes:	Transit <input checked="" type="checkbox"/> Truck <input type="checkbox"/> School <input type="checkbox"/> Bicycle <input type="checkbox"/>	
Roadway Width	3.44	(m)	Detour Length Around Bridge	5	(km)
Skew Angle	0	(Degrees)	Direction of Structure	West-East	
No. of Spans	1		Fill on Structure	0	(m)
Span Lengths	24.6				(m)

6.2 Historical Data

Year Built	1974	Year of Last Major Rehab.	
Last OSIM Inspection	2012	Last Evaluation	Unknown
Last Enhanced OSIM Inspection	Unknown	Current Load Limit	5 (tonnes)
Enhanced Access Equipment			
Last Underwater Inspection	Unknown	Load Limit By-Law #	Not Applicable/Unknown
Last Condition Survey	Unknown	By-Law Expiry Date	Not Applicable/Unknown
Rehabilitation History	1974 - Bridge collapsed on September 23 and was replaced with a Bailey Bridge loaned from MTO in October 1974. 1996- Stringers and timber deck replaced. 2003 - Raker Bolts, timber wearing surface, transoms, sway bracing replaced - Partial replacement of timber curb		

6. OSIM Reporting (cont.)

6.3 Scheduled Improvements

Regional Priority Number

Programmed Work Year

Nature of Program Work

6.4 Appraisal Indices

Comments

Fatigue

Seismic

Scour

Flood

Geometrics

Barrier

Curb

Load Capacity

6. OSIM Reporting (cont.)

6.5 Field Inspection Information

Date of Inspection	April-14-14	Type of Inspection	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector	Lin Yu			
Others in Party	None			
All Equipment Used	Hammer, Camera			
Weather	Sunny			
Temperature	5 to 10 C			

6.6 Additional Investigations Required

	None	Normal	Urgent	Est. Cost
Detailed Deck Condition Survey	X			
Non-Destructive Delamination Survey of Asphalt Covered Deck	X			
Concrete Substructure Condition Survey	X			
Detailed Coating Condition Survey	X			
Detailed Timber Investigation	X			
Post-Tensioned Strand Investigation	X			
Underwater Investigation	X			
Fatigue Investigation	X			
Seismic Investigation	X			
Structure Evaluation	X			
Monitoring of Deformations, Settlements and Movements			X	
Other* None	X			
Next Detailed Visual Inspection	April, 2016	Total Est. Cost		

The major concerns at this site are structural inadequacy of structure, water encroaching against abutments, road constriction, structural inadequacy of barriers, absence of a pedestrian access, absence of a traffic barrier, progressive undermining of the northwest retaining wall, severe failure of the northwest embankment, partial failure of northeast embankment, structural inadequacy of signage, severe corrosion of the bearing plates, isolated severe corrosion of the bottom chords at the ends and west end verticals, partial poor condition and progressive deterioration of the bearing seats and progressive deterioration of the masonry retaining walls.

Suspected Performance Deficiencies		06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
01 Load carrying capacity	07 Jammed expansion joint	13 Flooding/channel blockage	
02 Excessive deformations (deflections & rotations)	08 Pedestrian/vehicular hazard	14 Undermining of foundation	
03 Continuing settlement	09 Rough riding surface	15 Unstable embankments	
04 Continuing movements	10 Surface ponding	16 Other	
05 Seized bearings	11 Deck drainage		
Maintenance Needs			
00 None	06 Bridge Bearing Maintenance	12 Bridge Surface Repair	
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges	
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing	
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal	
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage	
05 Bridge Deck Joint Repair	11 Animal/Pest Control	17 Other	

* eg. monitoring crack widths, trip hazards, issues impacting pedestrian or vehicular control

6. OSIM Reporting (cont.)

6.7 Element Data

6.7.1 West Approach - Approach

Element Group:	West Approach			Length:	N/A		
Element Name:	Approach			Width:	N/A		
Location:	Single Element			Height:	N/A		
Material:	Asphalt			Count:	N/A		
Element Type:	Primary Element			Total Quantity:	5.81		
Environment:	Severe			Limited Inspection	<input type="checkbox"/>		
Protection System:	Edge Sealing				Performance Deficiencies		Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	tonnes	0	5.81	0	0	00	00
Comments:	None.						

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.2 East Approach - Approach

Element Group:	East Approach			Length:	N/A		
Element Name:	Approach			Width:	N/A		
Location:	Single Element			Height:	N/A		
Material:	Asphalt			Count:	N/A		
Element Type:	Primary Element			Total Quantity:	5.81		
Environment:	Severe			Limited Inspection	<input type="checkbox"/>		
Protection System:	Edge Sealing				Performance Deficiencies		Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	tonnes	0	5.81	0	0	00	00
Comments:	None.						

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.3 West Approach - Slab

Element Group:	West Approach					Length:	6		
Element Name:	Slab					Width:	3.6		
Location:	Single Element					Height:	0.12		
Material:	Asphalt					Count:	1		
Element Type:	Any					Total Quantity:	21.6		
Environment:	Severe					Limited Inspection	<input type="checkbox"/>		
Protection System:	None							Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor				
	m2	0	21.6	0	0			00	00
Comments:	None.								

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.4 East Approach - Slab

Element Group:	East Approach				Length:	6	
Element Name:	Slab				Width:	3.6	
Location:	Single Element				Height:	0.12	
Material:	Asphalt				Count:	1	
Element Type:	Any				Total Quantity:	21.6	
Environment:	Severe				Limited Inspection	<input type="checkbox"/>	
Protection System:	None					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	m2	0	21.6	0	0	00	00
Comments:	None.						

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.5 West Approach - Wearing Surface

Element Group:	West Approach			Length:	6		
Element Name:	Wearing Surface			Width:	3.6		
Location:	Single Element			Height:	0.15		
Material:	Asphalt			Count:	1		
Element Type:	Any			Total Quantity:	21.6		
Environment:	Severe			Limited Inspection	<input type="checkbox"/>		
Protection System:	Edge Sealing					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	m2	0	21.6	0	0	00	00
Comments:	None.						

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.6 East Approach - Wearing Surface

Element Group:	East Approach			Length:	6		
Element Name:	Wearing Surface			Width:	3.6		
Location:	Single Element			Height:	0.15		
Material:	Asphalt			Count:	1		
Element Type:	Any			Total Quantity:	21.6		
Environment:	Severe			Limited Inspection	<input type="checkbox"/>		
Protection System:	Edge Sealing					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	m2	0	21.6	0	0	00	00
Comments:	None.						

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.7 Deck - Deck

Element Group:	Deck					Length:	N/A	
Element Name:	Deck					Width:	N/A	
Location:	Single Element					Height:	N/A	
Material:	Timber					Count:	N/A	
Element Type:	Primary Element					Total Quantity:	8	
Environment:	Severe					Limited Inspection	<input type="checkbox"/>	
Protection System:	None						Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor			
	tonnes	0	7.2	0.4	0.4		00	00
Comments:	Isolated severe checking noted.							

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.8 Deck - Soffit Ends

Element Group:	Deck					Length:	2	
Element Name:	Soffit Ends					Width:	3.44	
Location:	Single Element					Height:	N/A	
Material:	Timber					Count:	2	
Element Type:	Any					Total Quantity:	13.8	
Environment:	Severe					Limited Inspection	<input type="checkbox"/>	
Protection System:	None						Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor			
	m2	0	13.8	0	0		00	00
Comments:	None.							

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



South End. Showing typical fair condition

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.9 Deck - Interior Soffit

Element Group:	Deck					Length:	20.6	
Element Name:	Interior Soffit					Width:	2.24	
Location:	Single Element					Height:	N/A	
Material:	Timber					Count:	1	
Element Type:	Any					Total Quantity:	46.1	
Environment:	Moderate					Limited Inspection	<input checked="" type="checkbox"/>	
Protection System:	None							
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs	
	m2	0	46.1	0	0	00	00	
Comments:	Deck underside was not inspected due to water level in 2014.							

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.10 Deck - Top Surface

Element Group:	Deck					Length:	24.6
Element Name:	Top Surface					Width:	3.44
Location:	Single Element					Height:	0.14
Material:	Timber					Count:	1
Element Type:	Any					Total Quantity:	84.6
Environment:	Severe					Limited Inspection	<input type="checkbox"/>
Protection System:	None					Performance Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor	Maintenance Needs	
	m2	0	76.14	4.23	4.23	00	00
Comments:	Isolated severe checking noted.						

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Top Surface. Showing isolated severe deterioration.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.11 West Transverse Joint - Transverse Joint

Element Group:	West Transverse Joint					Length:	N/A	
Element Name:	Transverse Joint					Width:	N/A	
Location:	Single Element					Height:	N/A	
Material:	Any					Count:	N/A	
Element Type:	Open					Total Quantity:	5.5	
Environment:	Benign					Limited Inspection	<input type="checkbox"/>	
Protection System:	None						Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor			
	m	0	5.5	0	0		00	00
Comments:	None.							

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : None



West View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.12 East Transverse Joint - Transverse Joint

Element Group:	East Transverse Joint			Length:	N/A		
Element Name:	Transverse Joint			Width:	N/A		
Location:	Single Element			Height:	N/A		
Material:	Any			Count:	N/A		
Element Type:	Open			Total Quantity:	5.5		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	m	0	5.5	0	0	00	00
Comments:	None.						

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : None



East View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.13 Sidewalk/Curb/Median - SouthSidewalk/Curb/Median

Element Group:	Sidewalk/Curb/Median					Length:	N/A	
Element Name:	SouthSidewalk/Curb/Median					Width:	N/A	
Location:	South					Height:	N/A	
Material:	Timber					Count:	N/A	
Element Type:	Primary Element					Total Quantity:	0.5	
Environment:	Severe					Limited Inspection	<input type="checkbox"/>	
Protection System:	None						Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor			
	tonnes	0	0.42	0.08	0		00	00
Comments:	None.							

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



Overall Surface. Showing generally good condition

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.14 Sidewalk/Curb/Median - North Curb

Element Group:	Sidewalk/Curb/Median					Length:	24.6
Element Name:	North Curb					Width:	0.19
Location:	North					Height:	0.19
Material:	Timber					Count:	2
Element Type:	Any					Total Quantity:	18.6
Environment:	Severe					Limited Inspection	<input type="checkbox"/>
Protection System:	None					Performance Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor	Maintenance Needs	
	m2	0	15.81	2.79	0	00	00
Comments:	None.						

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



North Surface. Showing generally fair condition

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.15 Barrier - Barrier

Element Group:	Barrier				Length:	N/A	
Element Name:	Barrier				Width:	N/A	
Location:	Single Element				Height:	N/A	
Material:	Timber				Count:	N/A	
Element Type:	Primary Element				Total Quantity:	0.2	
Environment:	Severe				Limited Inspection	<input type="checkbox"/>	
Protection System:	None					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	tonnes	0	0	0	0.2	16	17
Comments:	There is no traffic barrier (only some timber railing was noted). Approach traffic barrier is present.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☒

Recommended Work : Ancillary Replacement



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.16 Signage - Signage

Element Group:	Signage					Length:	N/A	
Element Name:	Signage					Width:	N/A	
Location:	Single Element					Height:	N/A	
Material:	Aluminum					Count:	6	
Element Type:	Primary Element					Total Quantity:	6	
Environment:	Severe					Limited Inspection	<input type="checkbox"/>	
Protection System:	None						Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor			
	all	0	0	6	0		16	17
Comments:	Much suitable signage should be in place for this specific situation (narrow structure, one lane, speed limit signs are not present).							

Urgency : None ☐ 6-10 years ☐ 1-5 years ☐ < 1 year ☒ Urgent ☐

Recommended Work : Ancillary Replacement



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.17 Truss - Truss

Element Group:	Truss					Length:	N/A	
Element Name:	Truss					Width:	N/A	
Location:	Single Element					Height:	N/A	
Material:	Steel					Count:	N/A	
Element Type:	Primary Element					Total Quantity:	25	
Environment:	Severe					Limited Inspection	<input type="checkbox"/>	
Protection System:	None							
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs	
	tonnes	0	23.25	1.25	0.5	00	00	

Comments: The truss (bailey structure) is in good condition except for the west end verticals (exhibiting intermittent severe rust pack) and the bottom chords close to the bearing areas (exhibiting severe corrosion). Further deterioration of these elements may result in some marginal loss of strength and end panels may require replacement.

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



North Side.



South Side.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.18 Truss - Bottom Chords

Element Group:	Truss					Length:	24.4
Element Name:	Bottom Chords					Width:	0.05
Location:	Single Element					Height:	0.1
Material:	Steel					Count:	8
Element Type:	Any					Total Quantity:	78.1
Environment:	Severe					Limited Inspection	<input type="checkbox"/>
Protection System:	None					Performance Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor	Maintenance Needs	
	N/A	0	74.98	1.56	1.56	00	00
Comments:	Isolated severe corrosion noted; however, progressive deterioration will result in loss of strength. The severe corrosion is concentrated at the ends close to the bearing plates.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



South Surface. Showing generally good condition



Underside Surface. Showing isolated severe corrosion.



Underside View . Showing isolated severe corrosion.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.19 Truss - Diagonals

Element Group:	Truss			Length:	1		
Element Name:	Diagonals			Width:	0.1		
Location:	Single Element			Height:	0.05		
Material:	Steel			Count:	256		
Element Type:	Any			Total Quantity:	105		
Environment:	Severe			Limited Inspection	<input type="checkbox"/>		
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	m2	0	105	0	0	00	00
Comments:	None.						

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Overall View .

6. OSIM Reporting (cont.)


6.7 Element Data (cont.)

6.7.20 Truss - Top Chords

Element Group:	Truss			Length:	24.4		
Element Name:	Top Chords			Width:	0.05		
Location:	Single Element			Height:	0.1		
Material:	Steel			Count:	8		
Element Type:	Any			Total Quantity:	80.5		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	Epoxy Coating					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	m2	0	80.5	0	0	00	00
Comments:	None.						

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



North Surface. Showing generally moderate corrosion



South Surface. Showing widespread medium corrosion

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.21 Truss - Connections

Element Group:	Truss			Length:	N/A		
Element Name:	Connections			Width:	N/A		
Location:	Single Element			Height:	N/A		
Material:	High Strength Steel			Count:	190		
Element Type:	Bolted			Total Quantity:	190		
Environment:	Severe			Limited Inspection	<input type="checkbox"/>		
Protection System:	Galvanized Steel					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	each	0	190	0	0	00	00
Comments:	None.						

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



North Side.



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.22 Truss - Verticals

Element Group:	Truss					Length:	1.55
Element Name:	Verticals					Width:	0.1
Location:	Single Element					Height:	0.05
Material:	Steel					Count:	96
Element Type:	Any					Total Quantity:	38.4
Environment:	Severe					Limited Inspection	<input type="checkbox"/>
Protection System:	None					Performance Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor	Maintenance Needs	
	m2	0	36.86	0.77	0.77	16	07
Comments:	The west end verticals exhibits isolated severe rust pack (end panels may need to be replaced).						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



West End.



West End. Showing isolated severe corrosion.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.23 Floor Beams - Floor Beams

Element Group:	Floor Beams			Length:	3.85		
Element Name:	Floor Beams			Width:	0.12		
Location:	Single Element			Height:	0.26		
Material:	Timber			Count:	19		
Element Type:	Primary Element			Total Quantity:	73.2		
Environment:	Severe			Limited Inspection	<input type="checkbox"/>		
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	m2	0	71	2.2	0	00	00
Comments:	None.						

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



Overall .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.24 Floor Beams - Floor Beam Ends

Element Group:	Floor Beams					Length:	3.85	
Element Name:	Floor Beam Ends					Width:	0.12	
Location:	Single Element					Height:	0.26	
Material:	Steel					Count:	2	
Element Type:	Any					Total Quantity:	11.2	
Environment:	Moderate					Limited Inspection	<input checked="" type="checkbox"/>	
Protection System:	None							
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs	
	m2	0	10.86	0.34	0	00	00	
Comments:	None.							

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



West End. Showing generally good condition

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.25 Floor Beams - Intermediate Floor Beams

Element Group:	Floor Beams					Length:	3.85		
Element Name:	Intermediate Floor Beams					Width:	0.12		
Location:	Single Element					Height:	0.26		
Material:	Steel					Count:	17		
Element Type:	Any					Total Quantity:	62		
Environment:	Moderate					Limited Inspection	<input type="checkbox"/>		
Protection System:	None							Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor				
	m2	0	60.14	1.86	0			00	00
Comments:	None.								

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.26 Stringers - Stringers

Element Group:	Stringers					Length:	24.4	
Element Name:	Stringers					Width:	0.05	
Location:	Single Element					Height:	0.1	
Material:	Steel					Count:	15	
Element Type:	Primary Element					Total Quantity:	15	
Environment:	Moderate					Limited Inspection	<input type="checkbox"/>	
Protection System:	Galvanized Steel							
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs	
	each	0	13.65	1.35	0	00	00	
Comments:	Stringers exhibit medium corrosion on the top and bottom flange.							

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.27 Stringers - Middle Stringers

Element Group:	Stringers					Length:	24.4
Element Name:	Middle Stringers					Width:	0.05
Location:	Single Element					Height:	0.1
Material:	Steel					Count:	15
Element Type:	Any					Total Quantity:	15
Environment:	Benign					Limited Inspection	<input type="checkbox"/>
Protection System:	None					Performance Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor	Maintenance Needs	
	each	0	13.35	1.65	0	00	00
Comments:	Stringers exhibit medium corrosion on the top and bottom flange.						

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Underside Surface. Showing isolated medium corrosion.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.28 Bracing - Bracing

Element Group:	Bracing			Length:	5.2		
Element Name:	Bracing			Width:	N/A		
Location:	Single Element			Height:	N/A		
Material:	Steel			Count:	24		
Element Type:	Primary Element			Total Quantity:	24		
Environment:	Benign			Limited Inspection	<input checked="" type="checkbox"/>		
Protection System:	Galvanized Steel						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	each	0	24	0	0	00	00
Comments:	None.						

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.29 Bracing - East End Bracing

Element Group:	Bracing			Length:	5.2		
Element Name:	East End Bracing			Width:	0.05		
Location:	East			Height:	0.1		
Material:	Steel			Count:	2		
Element Type:	Any			Total Quantity:	2		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	Galvanized Steel						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	each	0	2	0	0	00	00
Comments:	None.						

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



East End.



6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.30 Bracing - Intermediate Bracing

Element Group:	Bracing			Length:	5.2		
Element Name:	Intermediate Bracing			Width:	N/A		
Location:	Single Element			Height:	N/A		
Material:	Steel			Count:	20		
Element Type:	Any			Total Quantity:	20		
Environment:	Benign			Limited Inspection	<input checked="" type="checkbox"/>		
Protection System:	Galvanized Steel				Performance		
Condition Data:	Units	Exc.	Good	Fair	Poor	Deficiencies	Maintenance Needs
	each	0	20	0	0	00	00
Comments:	None.						

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Underside Surface. Showing generally good condition

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.31 Bracing - West End Bracing

Element Group:	Bracing			Length:	5.2		
Element Name:	West End Bracing			Width:	0.05		
Location:	West			Height:	0.1		
Material:	Steel			Count:	2		
Element Type:	Any			Total Quantity:	2		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	Galvanized Steel						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	each	0	2	0	0	00	00
Comments:	None.						

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



West End. Showing generally good condition

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.32 West Abutment - Abutment

Element Group:	West Abutment				Length:	N/A	
Element Name:	Abutment				Width:	N/A	
Location:	Single Element				Height:	N/A	
Material:	Masonry				Count:	N/A	
Element Type:	Primary Element				Total Quantity:	46	
Environment:	Benign				Limited Inspection	<input type="checkbox"/>	
Protection System:	None					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	tonnes	0	25.3	11.5	9.2	16	17
Comments:	Bearing plates are affected by severe corrosion and the thin concrete layer intended probably as a bearing area is in partial poor condition and progressively deteriorates (this may eventually lead to slight superstructure settlement). Isolated medium to severe loss of mortar and splitting also noted along the bottom side of the abutment wall.						
Urgency :	None <input type="checkbox"/>	6-10 years <input type="checkbox"/>	1-5 years <input checked="" type="checkbox"/>	< 1 year <input type="checkbox"/>	Urgent <input type="checkbox"/>		
Recommended Work :	Defer to Element Level						



6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.33 East Abutment - Abutment

Element Group:	East Abutment				Length:	N/A	
Element Name:	Abutment				Width:	N/A	
Location:	Single Element				Height:	N/A	
Material:	Masonry				Count:	N/A	
Element Type:	Primary Element				Total Quantity:	46	
Environment:	Benign				Limited Inspection	<input type="checkbox"/>	
Protection System:	None					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	tonnes	0	25.3	11.5	9.2	16	17

Comments: Bearing plates are affected by severe corrosion and the thin concrete layer intended probably as a bearing area is in partial poor condition and progressively deteriorates (this may eventually lead to slight superstructure settlement). Isolated medium to severe loss of mortar and splitting also noted along the bottom side of the abutment wall.

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : [Defer to Element Level](#)



East Side.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.34 West Abutment - Bottom Abutment Wall

Element Group:	West Abutment			Length:	N/A		
Element Name:	Bottom Abutment Wall			Width:	0.5		
Location:	Bottom			Height:	1		
Material:	Masonry			Count:	1		
Element Type:	Any			Total Quantity:	0.5		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	m2	0	0	0	0.5	00	17
Comments:	Isolated severe splitting and spalling noted at the base.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Replacement



Bottom Surface. Showing isolated severe deterioration.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.35 East Abutment - Bottom Abutment Wall

Element Group:	East Abutment			Length:	N/A		
Element Name:	Bottom Abutment Wall			Width:	1.5		
Location:	Bottom			Height:	1		
Material:	Masonry			Count:	1		
Element Type:	Any			Total Quantity:	1.5		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	m2	0	0	0	1.5	00	17
Comments:	Isolated severe splitting and spalling noted at the base.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Replacement



East Surface. Showing isolated severe deterioration.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.36 West Abutment - Bearings

Element Group:	West Abutment					Length:	N/A	
Element Name:	Bearings					Width:	N/A	
Location:	Single Element					Height:	N/A	
Material:	Any					Count:	2	
Element Type:	Plate					Total Quantity:	2	
Environment:	Severe					Limited Inspection	<input type="checkbox"/>	
Protection System:	None							
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs	
	each	0	0	1	1	05	17	
Comments:	Bearing plates are affected by severe corrosion (this may eventually result in slight settlement of the superstructure).							

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Replacement



Overall View . Showing severe corrosion.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.37 East Abutment - Bearings

Element Group:	East Abutment					Length:	N/A	
Element Name:	Bearings					Width:	N/A	
Location:	Single Element					Height:	N/A	
Material:	Any					Count:	2	
Element Type:	Plate					Total Quantity:	2	
Environment:	Severe					Limited Inspection	<input type="checkbox"/>	
Protection System:	None							
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs	
	each	0	0	1	1	05	17	
Comments:	Bearing plates are affected by severe corrosion (this may eventually result in slight settlement of the superstructure).							

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Replacement



East Side. Showing severe corrosion.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.38 West Abutment - Bearing Seats

Element Group:	West Abutment				Length:	N/A	
Element Name:	Bearing Seats				Width:	N/A	
Location:	Single Element				Height:	N/A	
Material:	Cast-In-Place Concrete				Count:	N/A	
Element Type:	Ledge				Total Quantity:	2	
Environment:	Moderate				Limited Inspection	<input type="checkbox"/>	
Protection System:	None					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	count	0	1	0.6	0.4	03	17
Comments:	Bearing plates were originally placed on a thin concrete layer, which is now in partially Poor condition, and slight settlements of the superstructure may be expected.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Loaded Deep Repair



Bottom Surface. Showing extensive severe corrosion.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.39 East Abutment - Bearing Seats

Element Group:	East Abutment				Length:	N/A	
Element Name:	Bearing Seats				Width:	N/A	
Location:	Single Element				Height:	N/A	
Material:	Cast-In-Place Concrete				Count:	N/A	
Element Type:	Ledge				Total Quantity:	2	
Environment:	Moderate				Limited Inspection	<input type="checkbox"/>	
Protection System:	None					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	count	0	1	0.6	0.4	03	17

Comments: Bearing plates were originally placed on a thin concrete layer, which is now in partial poor condition and slight settlements of the superstructure may be expected.

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Loaded Deep Repair



East Side. Showing poor condition.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.40 West Abutment - Abutment Wall

Element Group:	West Abutment					Length:	N/A	
Element Name:	Abutment Wall					Width:	5.9	
Location:	Single Element					Height:	2.2	
Material:	Masonry					Count:	1	
Element Type:	Any					Total Quantity:	12.5	
Environment:	Benign					Limited Inspection	<input type="checkbox"/>	
Protection System:	None						Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor			
	m2	0	9	2.5	1		00	17
Comments:	Isolated severe loss of mortar noted (especially along the base).							

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Replacement



Side.



West Surface. Showing isolated severe deterioration.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.41 East Abutment - Abutment Wall

Element Group:	East Abutment					Length:	N/A	
Element Name:	Abutment Wall					Width:	5.9	
Location:	Single Element					Height:	2.2	
Material:	Masonry					Count:	1	
Element Type:	Any					Total Quantity:	11.5	
Environment:	Benign					Limited Inspection	<input type="checkbox"/>	
Protection System:	None						Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor			
	m2	0	8.86	2.07	0.57		00	17
Comments:	Isolated severe loss of mortar noted (especially along the base).							

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Replacement



East Side. Showing isolated severe spalling.



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.42 West Abutment - Ballast Wall

Element Group:	West Abutment			Length:	N/A		
Element Name:	Ballast Wall			Width:	5.9		
Location:	Single Element			Height:	0.5		
Material:	Timber			Count:	1		
Element Type:	Any			Total Quantity:	3		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None				Performance Deficiencies		Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	m2	0	1.95	0.75	0.3	16	17
Comments:	The west side exhibits severe deterioration.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Timber Replacement



Side. Showing severe deterioration.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.43 East Abutment - Ballast Wall

Element Group:	East Abutment			Length:	N/A		
Element Name:	Ballast Wall			Width:	5.9		
Location:	Single Element			Height:	0.5		
Material:	Timber			Count:	1		
Element Type:	Any			Total Quantity:	3		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	m2	0	3	0	0	00	00
Comments:	None.						

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : Timber Replacement



East Side.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.44 West Retaining Wall - NorthRetaining Wall

Element Group:	West Retaining Wall			Length:	N/A		
Element Name:	NorthRetaining Wall			Width:	N/A		
Location:	North			Height:	N/A		
Material:	Mass Concrete			Count:	N/A		
Element Type:	Gravity			Total Quantity:	18.29		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None				Performance Deficiencies		Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	tonnes	0	14.63	3.66	0	03	17
Comments:	Continuing settlement expected due to undermining.						

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



Northwest Side.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.45 West Retaining Wall - Vertical Surface

Element Group:	West Retaining Wall			Length:	8		
Element Name:	Vertical Surface			Width:	N/A		
Location:	Single Element			Height:	1.75		
Material:	Masonry			Count:	1		
Element Type:	Any			Total Quantity:	14		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	m2	0	0	14	0	16	17
Comments:	None.						

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Northwest Side.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.46 East Retaining Wall - SouthRetaining Wall

Element Group:	East Retaining Wall				Length:	N/A	
Element Name:	SouthRetaining Wall				Width:	N/A	
Location:	South				Height:	N/A	
Material:	Masonry				Count:	N/A	
Element Type:	Gravity				Total Quantity:	33.41	
Environment:	Benign				Limited Inspection	<input type="checkbox"/>	
Protection System:	None					Performance	Maintenance
Condition Data:	Units	Exc.	Good	Fair	Poor	Deficiencies	Needs
	tonnes	0	18.38	9.69	5.35	16	17
Comments:	There is severe loss of mortar; however, this does not appear to affect performance significantly.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.47 West Retaining Wall - SouthRetaining Wall

Element Group:	West Retaining Wall			Length:	N/A		
Element Name:	SouthRetaining Wall			Width:	N/A		
Location:	South			Height:	N/A		
Material:	Masonry			Count:	N/A		
Element Type:	Gravity			Total Quantity:	26.88		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None				Performance Deficiencies		Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	tonnes	0	11.29	14.25	1.34	16	17
Comments:	Some loss of wall at top and also loss of mortar noted.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.48 East Retaining Wall - South Vertical Surface

Element Group:	East Retaining Wall				Length:	8.7	
Element Name:	South Vertical Surface				Width:	N/A	
Location:	South				Height:	2	
Material:	Masonry				Count:	1	
Element Type:	Any				Total Quantity:	17.4	
Environment:	Benign				Limited Inspection	<input type="checkbox"/>	
Protection System:	None					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	m2	0	9.57	5.05	2.78	16	17
Comments:	There is severe loss of mortar; however, this does not appear to affect performance significantly.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.49 West Retaining Wall - South Vertical Surface

Element Group:	West Retaining Wall			Length:	8		
Element Name:	South Vertical Surface			Width:	N/A		
Location:	South			Height:	1.75		
Material:	Masonry			Count:	1		
Element Type:	Any			Total Quantity:	14		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	m2	0	5.88	7.42	0.7	16	17
Comments:	Some loss of wall at top and also loss of mortar noted.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.50 East Retaining Wall - NorthRetaining Wall

Element Group:	East Retaining Wall			Length:	N/A		
Element Name:	NorthRetaining Wall			Width:	N/A		
Location:	North			Height:	N/A		
Material:	Masonry			Count:	N/A		
Element Type:	Gravity			Total Quantity:	36.72		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None				Performance Deficiencies		Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	tonnes	0	23.87	11.02	1.84	00	17
Comments:	There is loss of mortar at the base of the retaining wall.						

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.51 West Retaining Wall - NorthRetaining Wall

Element Group:	West Retaining Wall			Length:	N/A		
Element Name:	NorthRetaining Wall			Width:	N/A		
Location:	North			Height:	N/A		
Material:	Masonry			Count:	N/A		
Element Type:	Gravity			Total Quantity:	26.88		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	tonnes	0	0	26.88	0	16	17
Comments:	Continuing settlement expected due to undermining.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : Ancillary Replacement



Northwest Side.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.52 East Retaining Wall - North Vertical Surface

Element Group:	East Retaining Wall					Length:	11.6	
Element Name:	North Vertical Surface					Width:	N/A	
Location:	North					Height:	2.2	
Material:	Masonry					Count:	1	
Element Type:	Any					Total Quantity:	25.5	
Environment:	Benign					Limited Inspection	<input type="checkbox"/>	
Protection System:	None						Performance	Maintenance
Condition Data:	Units	Exc.	Good	Fair	Poor	Deficiencies	Needs	
	m2	0	14.54	9.69	1.27	03	17	
Comments:	There is loss of mortar at the base of the retaining wall.							

Urgency : None ☐ 6-10 years ☒ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Side. Showing deterioration.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.53 West Retaining Wall - North Vertical Surface

Element Group:	West Retaining Wall				Length:	9.8	
Element Name:	North Vertical Surface				Width:	N/A	
Location:	North				Height:	1.3	
Material:	Mass Concrete				Count:	1	
Element Type:	Any				Total Quantity:	12.7	
Environment:	Benign				Limited Inspection	<input type="checkbox"/>	
Protection System:	None					Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor		
	m2	0	10.16	2.54	0	03	17
Comments:	Continuing settlement expected due to undermining.						

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : [See Primary Element](#)



Northwest Side.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.54 West Embankment - Embankment

Element Group:	West Embankment					Length:	N/A
Element Name:	Embankment					Width:	N/A
Location:	Single Element					Height:	N/A
Material:	Soil					Count:	1
Element Type:	Primary Element					Total Quantity:	1
Environment:	Severe					Limited Inspection	<input type="checkbox"/>
Protection System:	None					Performance Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor	Maintenance Needs	
	all	0	0.35	0.25	0.4	16	13

Comments: Northwest embankment has been almost entirely washed out by water flow and the substructure is now severely exposed which may eventually lead to substructure instability.

Urgency : None ☐ 6-10 years ☐ 1-5 years ☐ < 1 year ☒ Urgent ☐

Recommended Work : Replacement



Overall View .

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.55 East Embankment - Embankment

Element Group: [East Embankment](#)

Element Name: [Embankment](#)

Location: [Single Element](#)

Material: [Soil](#)

Element Type: [Primary Element](#)

Environment: [Severe](#)

Protection System: [None](#)

Length: [N/A](#)

Width: [N/A](#)

Height: [N/A](#)

Count: [1](#)

Total Quantity: [1](#)

Limited Inspection ☐

Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	all	0	0.6	0.2	0.2	16	13

Comments: [Partial failure noted along the northeast end.](#)

Urgency : [None](#) ☐

[6-10 years](#) ☐

[1-5 years](#) ☒

[< 1 year](#) ☐

[Urgent](#) ☐

Recommended Work : [Defer to Element Level](#)



East Side.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.56 West Embankment - Slope Protection

Element Group:	West Embankment					Length:	N/A
Element Name:	Slope Protection					Width:	N/A
Location:	Single Element					Height:	N/A
Material:	Foliation					Count:	1
Element Type:	Any					Total Quantity:	1
Environment:	Severe					Limited Inspection	<input type="checkbox"/>
Protection System:	None					Performance Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor	Maintenance Needs	
	all	0	0.35	0.25	0.4	16	13

Comments: Northwest embankment has been almost entirely washed out by water flow and the substructure is now severely exposed which may eventually lead to substructure instability.

Urgency : None ☐ 6-10 years ☐ 1-5 years ☐ < 1 year ☒ Urgent ☐

Recommended Work : [See Primary Element](#)



South west Side.



West Surface. Showing extensive severe deterioration.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.57 East Embankment - Slope Protection

Element Group: [East Embankment](#)

Element Name: [Slope Protection](#)

Location: [Single Element](#)

Material: [Foliation](#)

Element Type: [Any](#)

Environment: [Severe](#)

Protection System: [None](#)

Length: [N/A](#)

Width: [N/A](#)

Height: [N/A](#)

Count: [1](#)

Total Quantity: [1](#)

Limited Inspection ☐

Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	all	0	0.6	0.2	0.2	16	13

Comments: [Partial failure noted along the northeast end.](#)

Urgency : ☐ None

☐ 6-10 years

☒ 1-5 years

☐ < 1 year

☐ Urgent

Recommended Work : [Restoration](#)



East Side.



East Surface. Showing isolated severe failure.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.58 Foundation - Foundation

Element Group:	Foundation					Length:	N/A	
Element Name:	Foundation					Width:	N/A	
Location:	Single Element					Height:	N/A	
Material:	Steel Piles					Count:	1	
Element Type:	Primary Element					Total Quantity:	1	
Environment:	Benign					Limited Inspection	<input checked="" type="checkbox"/>	
Protection System:	None							
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs	
	each	0	0.8	0	0.2	00	00	
Comments:	<p>The waterbed along the west abutment exhibits medium degradation and taking into account that water flow encroaches against the substructure/footing it may be further affected by high volume of water. The condition of foundation should be regularly checked and proper measures should be taken if necessary.</p>							
Urgency :	None <input type="checkbox"/>		6-10 years <input type="checkbox"/>		1-5 years <input type="checkbox"/>		< 1 year <input checked="" type="checkbox"/>	
Recommended Work :	Reinstallation							
							Urgent <input type="checkbox"/>	



South View .



West Side.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.59 Foundation - NorthFoundation

Element Group:	Foundation					Length:	N/A	
Element Name:	NorthFoundation					Width:	N/A	
Location:	North					Height:	N/A	
Material:	Steel Piles					Count:	1	
Element Type:	Primary Element					Total Quantity:	1	
Environment:	Benign					Limited Inspection	<input checked="" type="checkbox"/>	
Protection System:	None							
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs	
	each	0	0.77	0.03	0.2	16	13	
Comments:	<p>The foundation of the north west retaining wall is being progressively undermined. The retaining wall may unstable during high volume water (in case of collapse the road system and the superstructure possibly may be severely affected). Further condition of the west foundation should be closely monitored.</p>							
Urgency :	None <input type="checkbox"/>		6-10 years <input type="checkbox"/>		1-5 years <input type="checkbox"/>		< 1 year <input checked="" type="checkbox"/>	
Recommended Work :	Reinstallation							
							Urgent <input type="checkbox"/>	



Northw est Side.



Northw est Side. Show ing deterioration.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.60 Watercourse - Watercourse

Element Group:	Watercourse					Length:	N/A	
Element Name:	Watercourse					Width:	N/A	
Location:	Single Element					Height:	N/A	
Material:	Any					Count:	1	
Element Type:	Straight					Total Quantity:	1	
Environment:	Benign					Limited Inspection	<input type="checkbox"/>	
Protection System:	None						Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor			
	all	0	0.65	0.1	0.25		16	17

Comments: Current span opening is shorter than the watercourse width and, water encroaches against abutments as a result. The condition of the west abutment should be closely monitored as its stability may be affected by high volume of water.

Urgency : None ☐ 6-10 years ☐ 1-5 years ☐ < 1 year ☒ Urgent ☐

Recommended Work : [Defer to Element Level](#)



Overall View . Showing condition.



6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.61 Watercourse - Bottom

Element Group:	Watercourse					Length:	N/A	
Element Name:	Bottom					Width:	N/A	
Location:	Single Element					Height:	N/A	
Material:	Soil					Count:	N/A	
Element Type:	Natural					Total Quantity:	120.54	
Environment:	Benign					Limited Inspection	<input type="checkbox"/>	
Protection System:	None						Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor			
	m2	0	96.43	24.11	0		16	13
Comments:	Medium degradation observed along west abutment (north west retaining wall may be undermined).							

Urgency : None ☐ 6-10 years ☐ 1-5 years ☒ < 1 year ☐ Urgent ☐

Recommended Work : None



West End. Showing medium deterioration.

6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.62 Watercourse - Downstream Section

Element Group:	Watercourse					Length:	N/A	
Element Name:	Downstream Section					Width:	N/A	
Location:	Single Element					Height:	N/A	
Material:	Soil					Count:	N/A	
Element Type:	Uncontrolled					Total Quantity:	60.27	
Environment:	Benign					Limited Inspection	<input type="checkbox"/>	
Protection System:	None						Performance Deficiencies	Maintenance Needs
Condition Data:	Units	Exc.	Good	Fair	Poor			
	m2	0	60.27	0	0		00	00
Comments:	None.							

Urgency : None ☒ 6-10 years ☐ 1-5 years ☐ < 1 year ☐ Urgent ☐

Recommended Work : None



6. OSIM Reporting (cont.)

6.7 Element Data (cont.)

6.7.63 Watercourse - Upstream Section

Element Group:	Watercourse			Length:	N/A		
Element Name:	Upstream Section			Width:	N/A		
Location:	Single Element			Height:	N/A		
Material:	Gravel			Count:	N/A		
Element Type:	Uncontrolled			Total Quantity:	60.27		
Environment:	Benign			Limited Inspection	<input type="checkbox"/>		
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor	Performance Deficiencies	Maintenance Needs
	m2	0	45.2	0	15.07	16	17

Comments: The width of the watercourse is bigger than the span opening and water encroaches against the abutments as a result (west abutment much more exposed than east).

Urgency : None ☐ 6-10 years ☐ 1-5 years ☐ < 1 year ☒ Urgent ☐

Recommended Work : Redirection



North Side. Showing condition.



7. Glossary

Abutment

A substructure unit which supports the end of the structure and retains the approach fill.

Asset

A collection of Components that are most economically and/or practically replaced, rehabilitated or maintained together under a single contract or initiative. The timing of such an initiative is weighed against the timing of treating other Assets.

Asset Value Contribution

The portion of the total replacement value attributable to a particular component.

Auxiliary Components

Any component which does not share in the load carrying capacity of the structure.

Benign

Not exposed. e.g. girders, pier caps (unless joints are leaking)

Bridge

A structure which provides a roadway or walkway for the passage of vehicles across an obstruction, gap or facility and which is greater than 3 m in span.

Chord

The upper and lower main longitudinal component in trusses or arches extending the full length of the structure.

Coating

The generic term for paint, lacquer, enamel, sealers, galvanizing, metallizing, etc.

Component

A major feature of an Asset that performs a particular function. Often in multiple occurrences.

Condition Index

See Net Asset Salvage Value (NASV).

Critical Quantity

The single quantity that defines the Element for costing purposes.

Culvert

Any bridge that is embedded in fill and is used to convey water, pedestrians or animals through it.

Deck Condition Survey

A detailed inspection of a concrete deck in accordance with The Structure Rehabilitation Manual.

Defect

An identifiable, unwanted condition that was not part of the original intent of design.

7. Glossary (cont.)

Detailed Visual Inspection

An element by element visual assessment of material defects, performance deficiencies and maintenance needs of a structure.

Deterioration

A defect that has occurred over a period of time.

Diagonals

Component which spans between the top and bottom chord of a truss or arch in a diagonal direction.

Distress

A defect produced by loading.

Element

A feature of a Component distinguished in terms of condition, material, base of measurement or unit cost of repair.

Engineer

A member or licensee of the Professional Engineers of Ontario.

Environment

An element's exposure to chloride contamination and freeze-thaw cycling

Estimated Remaining Service Life

The Remaining Service Life (RSL) is an estimate, in years, over which an element may remain in service without repair or replacement. It is assumed that the conditions to which the element has been exposed will not change significantly and is based solely on visual observation.

Estimated Remaining Service Life (ERSL)

This is an estimate, in years, as to how long an element can be expected to continue to perform satisfactorily without the predominant deficiency being addressed. In the case of a Primary Element, it is the time remaining before the element must be addressed at a Primary Element Level if nothing is done. It is based on judgment and experience and is tempered by the need to control liability of our clients. In cases where no physical testing results are available, ERSL's will tend to be more conservative. The ERSL assigned to a component represents the minimum ERSL assigned to any element comprising that component.

Evaluation

The determination of the load carrying capacity of structures in accordance with the requirements of the Ontario Highway Bridge Design Code or the Canadian Highway Bridge Design Code, when implemented.

Floor Beam

Transverse beams that span between trusses, arches or girders and transmit loads from the deck and stringers to the trusses, arches or girders.

7. Glossary (cont.)

Focus

At the element level, focus refers to the portion of the element in question. In most cases the focus is simply stated as "All" or, in other words, the entire element is being reported on under one designation. As elements deteriorate over time it is often desirable to differentiate between areas that are deteriorating more rapidly or differently. In other cases, elements are comprised of different materials and would be repaired differently as a result. These too should be separated and referred to by their focus. The focus of a primary element is always set to "All".

Highway

A common and public thoroughfare including street, avenue, parkway, driveway, square, place, bridge, designed and intended for, or used by, the general public for passage of vehicles, pedestrians or animals.

Lateral Bracing

Bracing which lies in the plane of the top or bottom chords or flanges and provides lateral stability and resistance to wind loads.

Maintenance

Any action which is aimed at preventing the development of defects or preventing deterioration of a structure or its components.

Masonry

Structure made up of natural stones separated by mortar joints, usually in uniform courses. Masonry in existing structures is usually in retaining walls, abutments, piers or arches.

Masonry Ashlar

Stone worked to a square shape or cut square with uniform coursing height and vertical joints staggered. The stone has a minimum course height of 200 mm set in joints with an average thickness of 10 mm or less.

Masonry Rubble

Stone masonry constructed with rough field stones or only roughly squared stones set in mortar joints with average thickness greater than 20 mm. Also any squared stone masonry in which the joints are greater than 20 mm, but less than 30 mm in thickness.

Masonry Squared Stone

Stone in natural bed thicknesses or roughly squared stones with course height less than 200 mm and joints greater than 10mm but not over 20mm.

Moderate

Exposed but element protected e.g. asphalt covered and waterproofed deck

Net Asset Salvage Value (NASV)

The current NASV of an asset is equal to its original dollar value minus the estimated cost of rehabilitating the asset back to its original condition. NASV changes continually with time, diminishing in step with the continued deterioration of the asset. It is important to recognize that whether a component such as a bridge deck is replaced or fully repaired it will still be reset to its full Asset Value Contribution. Recognition of the difference in longevity of the two strategies will be revealed by the subsequent behaviour of the post-rehabilitation performance curve. Expressed as a percentage it forms the rationale for the overall Condition Index of the asset.

7. Glossary (cont.)

Owner

An agency having jurisdiction and control over the bridge.

Performance Curve

A plot of Condition Index over time. The vertical scale represents Condition Index from 0 to 100, the horizontal scale represents time in years. The plot will reflect the Condition Index of the Asset since original construction to the present and from the present to the end of the analysis period. The impact of rehabilitative work (already carried out since construction as well as that planned for the future) will be reflected in the curve as will the anticipated subsequent performance of that Rehabilitation.

Person

An individual, board, commission, partnership or corporation, including a municipal corporation, and employees, agents, successors and assigns of any of them.

Plans

All drawings, descriptions and specifications, being parts of the contract, and all drawings and descriptions produced by the constructor for the erection of a bridge or structure, and all revisions thereto.

Portal Bracing

Overhead bracing at the ends of a through truss or arch and provides lateral stability and shear transfer between trusses.

Primary Components

The main load carrying components of the structure.

Primary Element

The elemental equivalent of the component it comprises. For example, an Abutment consists of the elements, Wngwalls, Abutment Wall, Ballast Wall, Bearings. It also has an element called "Abutment". This element is needed so that costing (which is carried out at the element level) can account for replacement of the entire component. This element is referred to as the Primary Element.

Rehabilitation

Any modification, alteration, retrofitting or improvement to a structure sub-system or to the structure which is aimed at correcting existing defects or deficiencies. May involve repair of existing elements or complete replacement.

Repair

Any modification, alteration, retrofitting or improvement to a component of the structure which is aimed at correcting existing defects or deficiencies.

Replacement Cost

Replacement Cost is the expenditure required to build, on a new site, or replace at an existing site, a bridge that meets all present and projected requirements of the site, community and current codes.

Replacement Value

Traditionally, Replacement Value refers to the cost in today's dollars for the identical replacement of an existing bridge. In other words, it is the value of the existing installation.

7. Glossary (cont.)

Retaining Wall

Any structure that holds back fill and is not connected to a bridge.

Secondary Components

Any component which helps to distribute loads to primary components, or carries wind loads, or stabilizes primary components.

Severe

Exposed and element not protected e.g. Exposed concrete deck, Barrier Wall

Sign Support

A metal, concrete or timber structure, including supporting brackets, service walks and mechanical devices where present, which support a luminaire, sign or traffic signal and which span or extend over a highway.

Span

The horizontal distance between adjacent supports of the superstructure of a bridge, or the longest horizontal dimension of the cross-section of a culvert or tunnel taken perpendicular to the walls.

Stringers

Stringers span between floor beams and provide the support for the deck above.

Structure

Bridge, culvert, tunnel, retaining wall or sign support.

Suspected Performance Deficiency

A Suspected Performance Deficiency should be recorded during an inspection, if an element's ability to perform its intended function is in question, and one or more performance defects exist.

Sway Bracing

Vertical bracing spanning between through trusses or arches, or outside of half-through trusses or arches and providing lateral stability and shear transfer between the trusses or arches.

Tunnel

Any bridge that is constructed through existing ground, and is used to convey highway or railway traffic through it.

Utility

Refers to a local utility such as hydro, gas, telephone etc. not part of the structure itself but rather utilizing it to provide passage. Typically carried between girders or hanging from the underside of the deck. Of significance only because the integrity of its connection to the structure impacts public safety.

Verticals

Components which span between the top and bottom chords of a truss or arch in the vertical direction.

7. Glossary (cont.)

Whisker Graphs

Simple frequency distribution charts that are intended, at a glance, to convey a comparative reference. They are shown on the Structure Summary to give the reader an immediate sense of how the bridge compares to the rest of the network based on various criteria.