Natural Heritage Photo Logs



Scoped Headwater Drainage Feature
Assessment (HDFA)
Representative Photo Log
(April 2, 2018)



# Scoped Headwater Drainage Feature Assessment (HDFA) Representative Photo Log (April 2, 2018)



Photo 1 (Photo Location 1) Reach HC-H7-R1

South-facing view from reach break – standing water conditions.



Photo 2 (Photo Location 2) Reach HC-H3-R2

North-facing (upstream view) of general conditions from reach break (change in feature type). Minimal flow was observed.



Photo 3 (Photo Location 2) Reach HC-H3-R2

South-facing (downstream view) of conditions - minimal flow, channelized feature type.



Photo 4 (Photo Location 3) Reach HC-H3-R2

Upstream view of conditions - minimal flow.





Photo 5 (Photo Location 3) Reach HC-H3-R2

Photo 6 (Photo Location 4) Reach HC-H3-R2

Downstream view of conditions - minimal flow.

Downstream view from reach break – minimal flow.



Photo 7 (Photo Location 5) Reach HC-H3-R3

Upstream view from reach break (change in feature type and flow condition) – wetland feature/standing water.



Photo 8 (Photo Location 6) Reach HC-H3-R3

South-facing (downstream) view of wetland feature.





Photo 9 (Photo Location 7) Reach HC-H3-R5

Photo 10 (Photo Location 8) Reach HC-H7-R1

North-facing (downstream view) towards Reach HC-H3-R4. Feature is dry and actively farmed.

North-facing (downstream view) towards reach (standing water).



Photo 11 (Photo Location 9) Reach HC-H7-R1

West-facing view of H7 upstream of reach break – no feature present.



Photo 12 (Photo Location 10) Laneway Wetland

West-facing view wetland – no downstream hydrologic connection was observed with H7.





Photo 13 (Photo Location 11) General Conditions

Photo 14 (Photo Location 12) HC-H6-R1

East-facing view – no features observed.

South-facing (downstream) view of conditions.



Photo 15 (Photo Location 13) HC-H5-R1



Photo 16 (Photo Location 14) HC-H5-R2

Downstream-facing view of wetland feature with standing water conditions.

West-facing (upstream) view of feature – dry with forested riparian vegetation.



Wetland Level and Quality Monitoring Stations Photo Log (2016 - 2017)



#### Wetland Level and Quality Monitoring Stations Photo Log (2016 – 2017)





Photo 1.
Wetland Station 1 – May 1, 2017.
(Photo provided by Matrix Solutions Inc.)

Photo 2.
Wetland Station 1 – August 10, 2017
(Photo provided by Matrix Solutions Inc.)







Photo 3.
Station 2 – May 1, 2017.
(Photo provided by Matrix Solutions Inc.)

Photo 4.
Station 2 – May 1, 2017
(Photo provided by Matrix Solutions Inc.)







Photo 6.
Station 2 – August 10, 2017
(Photo provided by Matrix Solutions Inc.)





Photo 7. Station 3 – April 18, 2017.

Photo 8. Station 3 – May 1, 2017







Photo 10. Station 3 – November 29, 2017





2017/05/01

Photo 11. Station 4 – April 18, 2017.

Photo 12. Station 4 – May 1, 2017







Photo 14. Station 4 – November 3, 2017









Photo 16. Station 5 – May 1, 2017



Photo 17. Station 5 – August 10, 2017



Photo 18. Station 5 – November 29, 2017







Photo 19. Station 6 – April 18, 2017.

Photo 20. Station 6 – May 1, 2017







Photo 22. Station 6 – November 3, 2017







Photo 23. Station 7 – April 18, 2017.

Photo 24. Station 7 – May 1, 2017







Photo 26. Station 7 – November 3, 2017





2017/05/01

Photo 27. Station 8 – April 18, 2017.

Photo 28. Station 8 – May 1, 2017



Photo 29. Station 8 – August 10, 2017



Photo 30. Station 8 – November 3, 2017





2017/05/01

Photo 31. Station 10 – April 18, 2017.

Photo 32. Station 10 – May 1, 2017







Photo 34. Station 10 – November 3, 2017





22/17/19/201

Photo 35. Station 11 – April 18, 2017.

Photo 36. Station 11 – May 1, 2017







Photo 38. Station 11 – November 3, 2017





Photo 39. Station 12 – April 18, 2017.

Photo 40. Station 12 – May 1, 2017



Photo 41. Station 12 – August 10, 2017



Photo 42. Station 12 – November 29, 2017





2017/05701

Photo 43. Station 13 – April 18, 2017.

Photo 44. Station 13 – May 1, 2017







Photo 46. Station 13 (New Location) - November 29, 2017





Photo 47. Station 14 – April 28, 2017.

Photo 48. Station 14 – May 1, 2017







Photo 50. Station 14 – November 3, 2017





08/10

Photo 51. Station 15 – April 28, 2017.

Photo 52. Station 15 – August 10, 2017







Photo 54. Station 15 – November 3, 2017



Terrestrial Monitoring Representative Photo Log (2016 - 2017)



#### **Terrestrial Monitoring: Representative Photo Log (2016 – 2017)**





Photo 1. Winter Wildlife – Deer Tracks at 2162 Gordon St. (March 17, 2017)

Photo 2. Winter Wildlife – Wild Turkey at 2162 Gordon St.





Photo 3.

Amphibian Movement Survey – Wood Frog on Transect 2 (March 27, 2017)

Photo 4.

Amphibian Movement Survey – Blue-spotted Salamander on Transect 3 (March 27, 2017)



Photo 5.
Basking Turtle Survey - Midland Painted Turtle observed at T7 (April 27, 2017)



Photo 6.

Amphibian Movement Survey – Eastern Newt on Transect 3 (October 4, 2017)





Photo 7. Turtle Survey – Ribbon Snake (April 27, 2017)



Photo 8.

Turtle Survey – Snapping Turtle (May 17, 2017)



Photo 9.

Deciduous Forest Community (FOD) near 128

Dallan (September 22, 2016)



Photo 10.
Graminoid Organic Shallow Marsh Ecosite (MAS3) at 24 Serena Lane (September 7, 2017)





Photo 11.

Duckweed Floating-leaved Shallow Aquatic Type (SAF1-3) at 2162 Gordon Street (July 21, 2017)



Photo 12.

Water Lily – Bullhead Lily Floating-leaved Shallow
Aquatic Type (SAF1-1) at 2162 Gordon Street
(August 17, 2016)



Photo 13.
East side of Submerged Shallow Aquatic (SAS)
Community at 1992 Gordon Street (July 21, 2016)



Photo 14.
West side of Submerged Shallow Aquatic (SAS)
Community at 1992 Gordon Street (September 22, 2016)





Photo 15. Seep at 2162 Gordon Street (March 17, 2017)