


- Site Area Boundary
- Water Body
- Watercourse
- Highway
- Road
- Physiography**
- 13: Eskers
- 7: Drumlins
- 6: Till Plains (Drumlinized)
- 3: Spillways
- 2: Till Moraines



Reference: Data obtained from GeoBase® used under license
 Chapman, L.J. and Pullam, D.F. 2007. Physiography of Southern Ontario, Ontario Geological Survey, Miscellaneous Release, Data 228 ISBN 978-1-4249-5158-1



Dougan and Associates
 Guelph Turfgrass Relocation EIS – Hydrogeology Assessment

Physiography Map

Date: 22 Oct 2015 Project: 22176 Technical: S. Davies Reviewer: S. Davies Drawn: C. Curry

Disclaimer: The information contained herein may be compiled from numerous third party materials that are subject to periodic change without prior notification. While every effort has been made by Matrix Solutions Inc. to ensure the accuracy of the information presented at the time of publication, Matrix Solutions Inc. assumes no liability for any errors, omissions, or inaccuracies in the third party material.

I:\Client\Guelph\22176\Figures and Tables\CH06\01 EIS Report\Figure_X-X-X-Physiography_Map.mxd